

V I K I N G O

Fiammato/Slubby

Ne 30/1 Nm 1/50000

COMPOSIZIONE

100% Cotone

IMPIEGO

Tessitura trama - Maglieria circolare

ATTENZIONI PARTICOLARI

Filato fiammato: in MAGLIERIA usare su finezze adeguate

Il filato si presenta con una melangiatura di colore irregolare e non omogenea quale sua caratteristica.

All'interno della stessa rocca si possono pertanto evidenziare anellature con differenze di colore che non sono da ritenersi difetto.

Consigliamo pertanto di non utilizzare il filato in mono caduta ma soltanto in lavorazioni che possano alternare il maggior numero di rocche per rendere più omogenea l'effetto finale. Inoltre tra lotto e lotto di produzioni diverse ci potranno essere leggere differenze di tonalità da ritenersi in tolleranza per questo tipo di filato

In TESSITURA utilizzare il mischiatrama

I colori non sono solidi alla sovratintura ed al candeggio.

MINIMI

Colori **STOCK SERVICE** : minimo una scatola

Maggiorazione prezzo applicata a quantità inferiori alla scatola. Altri colori se non disponibili: ordine minimo Kg 300

COMPOSITION

100% Cotton

APPLICATION

Weaving warp and weft - Circular Knitting

SPECIAL CARES

Slubby yarn: KNIT on adewuate gauges

The yarn features an uneven and non-homogeneous blend of colours.

The same bobbin may therefore contains rings of different colours, which should not be considered a defect. We therefore do not recommend using the yarn in a single feed machine, but only in processes that can alternate many bobbins to make the final effect more homogeneous.

There may also be slight differences in shade between one batch and the next, which should be considered in tolerance for this type of yarn.

Weft mixer is necessary to avoid colour stripes in WEAVING

Fastness of colours is not sufficient for over dyeing and bleaching.

MINIMUM

STOCK SERVICE colours: one box minimum

For quantity less than one box: extra charge. Other colours if not available: minimum order 300 Kgs

INFORMAZIONI TECNICHE / TECHNICAL INFORMATION

SOLIDITÀ FASTNESS	ISO	SCARICO SU COTONE DISCHARGE ON COTTON	DEGRADO COLOR CHANGING
LAVAGGIO IN ACQUA 40° C WASHING AT 40° C	105-C06	4	4
LAVAGGIO A SECCO DRY CLEANING	105-D01	4	4
SUDORE ACIDO-ALCALINO ACID-ALKALINE PERSPIRATION	105-E04	4	4
SFREGAMENTO/RUBBING REATTIVI A SECCO / DRY REATTIVI A UMIDO / WET HYDROSOL A UMIDO / WET	105-X12	3 - 4 3 - 4 2 - 3	4 4 3
LUCE ARTIFICIALE ARTIFICIAL LIGHT	105-B02	-	4

Note: valori medi / average values



Water
Temperature 40°



Do not
Bleach



Do not
Tumbler Dry



Steam Ironing
max 110°C



Dry Cleaning
mild Process

COTONIFICIO OLCESE FERRARI S.p.A.

Ufficio commerciale: Via Marzaghetta, 7 - 25030 Adro (BS) ITALY

Tel. +39 030 7458830

sales.office@olceseFerrari.it - www.olceseFerrari.it



STANDARD
100
951453.0
CENTROCOT
www.oeko-tex.com

