

T R O X X I

Nm 3/50000

COMPOSIZIONE

60% Cotone Pettinato - 30%Viscosa - 6%Lana - 4%Cashmere

IMPIEGO

Macchine Rettilinee finezza 12 ad 1 capo

ATTENZIONI PARTICOLARI

I colori non sono solidi alla sovratintura ed al candeggio.

ISTRUZIONI DI LAVAGGIO

Lavare in acqua a 30° con saponi neutri oppure a secco con solventi adatti.
In caso di maglieria rigata con colori forti e contrastanti lavare solo a secco.

CONSIGLI UTILI

Consigliamo l'utilizzo di questo articolo su rettilinea a 2 o più guidafile, per una distribuzione uniforme dell'effetto Mouliné.
Vista la particolare costruzione di questo articolo uno scarto del 5% deve essere considerato nei costi di smacchinatura.

Verificare sempre che il fiato sia idoneo all'uso al quale viene destinato.

All'inizio della produzione controllare attentamente i primi teli ed in caso di irregolarità del filato interrompere immediatamente la smacchinatura e contattare il nostro Ufficio Commerciale, la filatura riconoscerà solo kg.3 di filato smacchinato ed in nessun caso capi finiti e confezionati.

MINIMI

Quantità minime: richiedere supplementi all'ufficio vendite.

COMPOSITION

60% Combed Cotton - 30%Viscose - 6%Wool - 4%Cashmere

APPLICATION

Flat knitting machines 12 gauge 1 ply.

SPECIAL CARES

Fastness of colours is not sufficient for overdyeing and bleaching

WASHING INSTRUCTION

Wash in 30° water with neutral soap or dry clean with suitable solvents.

In case of striped knitting dry clean only.

USEFUL INSTRUCTION

Knitting this yarn on a flat bed knitting machine with two or more threadguides is recommended in order to get a homogeneous mouliné effect
Due to the peculiar yarn construction please always consider 5% material loss during the knitting process

Always ensure that the yarn is suitable for the end use for which it is intended

When starting production check knitted panels carefully. If yarn defects are noticed stop knitting immediately and contact our Sales Department
No claim will be accepted by the spinner for more than 3 Kilos of knitted yarn and in no case claims will be accepted on finished garments

MINIMUM

Minimum quantity: the surcharges have to be required to sales office.

FASTNESS

SOLIDITA' FASTNESS	ISO	SCARICO SU COTONE DISCHARGE ON COTTON	DEGRADO COLOR CHANGING
LAVAGGIO IN ACQUA A 40°C WASHING AT 40°C	105-C06	4	4
LAVAGGIO A SECCO DRY CLEANING	105-D01	4	4
SUDORE ACIDO-ALCALINO ACID-ALKALINE PERSPIRATION	105-E04	4	4
SFREGAMENTO/RUBBING SECCO/DRY UMIDO/WET	105-X12	3 - 4	4
LUCE ARTIFICIALE ARTIFICIAL LIGHT	105-B02	-	4



COTONIFICIO OLCESE FERRARI s.p.a.

Ufficio commerciale: Via Marzaghetta, 7 - 25030 Adro (BS) ITALY

Tel. +39 030 7458830 - fax +39 030 7458833

sales.office@olceseferrari.it - www.olceseferrari.it

feel
THE
YARN®

