

LOVE

Nm 3/50000

COMPOSIZIONE

90%Viscosa FSC - 10%Cashmere

IMPIEGO

Macchine Rettilinee finezza 12 ad 1 capo

ATTENZIONI PARTICOLARI

I colori non sono solidi alla sovratintura ed al candeggio.

ISTRUZIONI DI LAVAGGIO

Lavare in acqua a 30° con saponi neutri oppure a secco con solventi adatti.

In caso di maglieria rigata con colori forti e contrastanti lavare solo a secco.

CONSIGLI UTILI

Verificare sempre che il fiato sia idoneo all'uso al quale viene destinato.

All'inizio della produzione controllare attentamente i primi teli ed in caso di irregolarità del filato interrompere immediatamente la smacchinatura e contattare il nostro Ufficio Commerciale, la filatura riconoscerà solo kg.3 di filato smacchinato ed in nessun caso capi finiti e confezionati.

MINIMI

Quantità minime: richiedere supplementi all'ufficio vendite.

COMPOSITION

90% FSC Viscose - 10%Cashmere

APPLICATION

Flat knitting machines 12 gauge 1 ply.

SPECIAL CARES

Fastness of colours is not sufficient for overdyeing and bleaching

WASHING INSTRUCTION

Wash in 30° water with neutral soap or dry clean with suitable solvents.

In case of striped knitting dry clean only.

USEFUL INSTRUCTION

Always ensure that the yarn is suitable for the end use for which it is intended

When starting production check knitted panels carefully. If yarn defects are noticed stop knitting immediately and contact our Sales Department

No claim will be accepted by the spinner for more than 3 Kilos of knitted yarn and in no case claims will be accepted on finished garments

MINIMUM

Minimum quantity: the surcharges have to be required to sales office.

INFORMAZIONI TECNICHE / TECHNICAL INFORMATION

SOLIDITA' FASTNESS	ISO	SCARICO SU COTONE DISCHARGE ON COTTON	DEGRADO COLOUR CHANGING
LAVAGGIO IN ACQUA A 40°C WASHING AT 40°C	105-C06	4	4
LAVAGGIO A SECCO DRY CLEANING	105-D01	4	4
SUDORE ACIDO-ALCALINO ACID-ALKALINE PERSPIRATION	105-E04	4	4
SFREGAMENTO/RUBBING			
REATTIVI / A SECCO/DRY	105-X12	3 - 4	4
REATTIVI A UMIDO/WET		2 - 3	3
LUCE ARTIFICIALE ARTIFICIAL LIGHT	105-B02	-	4

Note: valori medi / average values



Il marchio della
gestione forestale
responsabile

Richiedi i prodotti certificati FSC®
Ask for FSC® Certified Product

COTONIFICIO OLCESE FERRARI S.p.A.

Ufficio commerciale: Via Marzaghetta, 7 - 25030 Adro (BS) ITALY

Tel. +39 030 7458830 - fax +39 030 7458833

sales.office@olceseFerrari.it - www.olceseFerrari.it



STANDARD
100
951453.0
CENTROCOT
www.oeko-tex.com